

PARTS DIAGRAM & PARTS LIST


ULTREX

80/112 LBS THRUST - 24/36 VOLT - 45"/52"/60" SHAFT

The parts diagram and parts list provides Minn Kota® WEEE compliance disassembly instructions. For more information about where you should dispose of your waste equipment for recycling and recovery and/or your European Union member state requirements, please contact your dealer or distributor from which your product was purchased. Tools required, but not limited to: flat head screwdriver, Phillips screwdriver, socket set, pliers, wire cutters.


ムサシ オーバーホール作業用資料: リールのメンテは "ムサシ オーバーホール" で検索

Motor Parts Diagram




ULTREX STEERING MODULE

Steering Module Parts Diagram



ULTREX FOOT PEDAL

Foot Pedal Parts Diagram



PARTS DIAGRAM & PARTS LIST

ULTREX MOUNT

Mount Parts Diagram

